

Product selector - how to use



Use the 'Connection Selector' on pages 18-19 to choose your required joint type.



Utilisez le 'sélectionneur de connexions' aux pages 18 et 19 pour choisir le type de joint requis.



Verwenden Sie zur Auswahl des gewünschten Verbindungstyps den „Anschluss-Auswahlführer“ auf den Seiten 18-19.



Usare il 'Selettore della Connessione', pagine 18-19, per scegliere il tipo di giunto richiesto.



Use el "Selector de conexiones" de las páginas 18-19 para elegir el tipo de empalme que necesita.

Cable to earth rod			CR1				
A	B	C					
mm fl	inches fl	mm					
12.7	1/2"	30"	88P10	CR1-6-12716	HCP66	CR1-3-12716	HCP92
12.7	1/2"	35	88P10	CR1-6-12720	HCP66	CR1-3-12720	HCP92
12.7	1/2"	35	88P10	CR1-6-12730	HCP66	CR1-3-12730	HCP92
12.7	1/2"	80	88P10	CR1-6-12750	HCP66	CR1-3-12750	HCP92
12.7	1/2"	80-66 n	88P10	CR1-6-12750C	HCP66	CR1-3-12750C	HCP92
12.7	1/2"	70	80P10	CR1-6-12770	HCP66	CR1-3-12770	HCP92
12.7	1/2"	80	80P10	CR1-6-12780	HCP66	CR1-3-12780	HCP92
12.7	1/2"	120	80P10	CR1-6-127120	HCP66	CR1-3-127120	HCP92
14.2	9/16"	16"	88P10	CR1-6-14216	HCP66	CR1-3-14216	HCP92
14.2	9/16"	20	88P10	CR1-6-14220	HCP66	CR1-3-14220	HCP92
14.2	9/16"	25	88P10	CR1-6-14230	HCP66	CR1-3-14230	HCP92
14.2	9/16"	80	80P10	CR1-6-14280	HCP66	CR1-3-14280	HCP92
14.2	9/16"	80-66 n	80P10	CR1-6-14280C	HCP66	CR1-3-14280C	HCP92
14.2	9/16"	70	80P10	CR1-6-14270	HCP66	CR1-3-14270	HCP92
14.2	9/16"	88	80P10	CR1-6-14288	HCP66	CR1-3-14288	HCP92
14.2	9/16"	120	80P10	CR1-6-142120	HCP66	CR1-3-142120	HCP92
14.2	9/16"	180	118P10	CR1-6-142180	HCP66	CR1-3-142180	HCP92
14.2	9/16"	185	118P10	CR1-6-142185	HCP66	CR1-3-142185	HCP92
14.2	9/16"	240	180P10	CR1-6-142240	HCP66	CR1-3-142240	HCP92

Find the required conductor sizes.

Recherchez la taille de conducteur requise.

Suchen Sie die gewünschten Leitergrößen.

Individuare le misure di conduttore richieste.

Busque los tamaños de conductor que necesita.

A	B	C
mm fl	inches fl	mm
12.7	1/2"	10



A powder cartridge is required for each joint to be made.

Une cartouche de poudre est nécessaire pour chaque joint.

Für jede herzustellende Verbindung ist ein Pulverpatrone erforderlich.

Per creare ogni giunto, è necessaria una cartuccia di polvere.

Necesita un cartucho de polvo para cada empalme que desee hacer.



A single mould is capable of producing on average 75 joints.

Un moule peut produire jusqu'à 75 joints.

Eine einzelne Form ist in der Lage, durchschnittlich 75 Verbindungen herzustellen.

Uno stampo è in grado di produrre una media di 75 giunti.

Un solo molde puede producir un promedio de 75 empalmes.



For handling the mould, or clamping the halves together.

Pour manipuler le moule, ou serrer les deux parties du moule.

Zum Umgang mit der Form oder Aneinanderklemmen der Hälften.

Per maneggiare lo stampo, o bloccare assieme le due parti dello stampo.

Para manejar el molde o unir las mitades con abrazaderas.



Less robust, more cost effective versions of the mould and handle clamp are available.

Il existe des versions moins robustes mais plus économiques du moule et des brides à poignée.

Auf Wunsch sind weniger robuste, preiswertere Versionen der Form und Griffklemmen verfügbar.

Sono disponibili versioni meno robuste e più economiche dello stampo e dei morsetti con manico.

También disponemos de otras versiones de molde e de abrazaderas de manivela menos resistentes y más baratas.



Sleeves are required when joining conductors smaller than 16mm².

Des manchons sont obligatoires pour le soudage de conducteurs de taille inférieure à 16mm².

Zum Verbinden von Leitern, deren Querschnitt kleiner als 16 mm² ist, sind Buchsen erforderlich.

Quando si uniscono conduttori di misura inferiore ai 16 mm², è necessario usare i manicotti.

Para empalmar conductores menores de 16 mm² se necesitan fundas.